



Buckle termination 40mm tapes



AA-B/PT

The termination buckle is used to connect the 40 mm poly tape to the high tension cable (HT) coming from the energizer. It is also used to connect 40 mm poly tapes to high tension cables (HT) whenever you need to go under gates.

Specifications:

Zinc buckle 40 x 60 x 60mm